

MX-Sensor_V3.40 Function List For JP Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining (Red: New, Yellow: Modify)

Special Declaration:

- 1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.
- 2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, O*=OBD partially supported, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Acura	NSX	06/2016-12/2020	315MHz		●	●	○	O	315MHz	Continental	●	●
Alfa Romeo	159	07/2005-12/2016	433MHz	939	●	●	○	A	433MHz	TRW	●	●
Alfa Romeo	4C	01/2013-12/2021	433MHz		●	●	●	O/A	433MHz	Schrader	●	●
Alfa Romeo	Giulia	07/2017-12/2026	315MHz 50554748		●	●	○	O/A	315MHz	Continental	●	●
Alfa Romeo	Giulia	01/2016-06/2017	315MHz		●	●	●	O/A	315MHz	Continental	●	●
Alfa Romeo	Giulietta	01/2010-12/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Alfa Romeo	Stelvio	01/2018-12/2026	315MHz		●	●	○	O/A	315MHz	Continental	●	●
Alfa Romeo	Stelvio	01/2017-12/2017	315MHz		●	●	●	O/A	315MHz	Continental	●	●
Alfa Romeo	Tonale	01/2022-06/2026	433MHz 68339096AB		●	●	○	O/A	433MHz	Continental	●	●
Alfa Romeo	Tonale	01/2022-12/2025	433MHz 50554747		●	●	○	O/A	433MHz	Continental	●	●
Alpina	B3	07/2022-06/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Alpina	B3	07/2022-06/2026	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
Alpina	B3	07/2022-06/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B3	03/2014-06/2019	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
Alpina	B3	09/2009-03/2014	433MHz		●	●	○	O*/A	433MHz	Huf/Beru	●	●
Alpina	B3	03/2006-08/2009	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B4	09/2020-12/2023	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B4	03/2014-07/2020	433MHz		●	●	○	A	433MHz	Continental	●	●
Alpina	B5	11/2021-06/2024	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
Alpina	B5	11/2021-06/2024	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Alpina	B5	11/2021-06/2024	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B5	01/2017-06/2024	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
Alpina	B5	03/2014-12/2016	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B5	02/2010-02/2014	433MHz		●	●	○	O*/A	433MHz	Huf/Beru	●	●
Alpina	B5	01/2005-12/2014	433MHz 36236798726		●	●	○	O*/A	433MHz	Huf/Beru	●	●
Alpina	B6	03/2014-06/2018	433MHz		●	●	○	O*/A	433MHz	Huf/Beru	●	●
Alpina	B6	12/2010-02/2014	433MHz		●	●	○	O*/A	433MHz	Huf/Beru	●	●
Alpina	B6	03/2006-11/2010	433MHz		●	●	○	O*/A	433MHz	Huf/Beru	●	●
Alpina	B7	07/2015-07/2022	433MHz		●	●	○	A	433MHz	Schrader	●	●

Alpina	B7	07/2015-07/2022	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	B7	09/2010-02/2014	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
Alpina	B7	01/2006-08/2010	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
Alpina	B8	01/2021-06/2026	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	B8	01/2021-06/2026	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	D3	07/2022-06/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Alpina	D3	07/2022-06/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D3	09/2009-02/2014	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
Alpina	D3	06/2005-08/2009	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D4	02/2022-06/2026	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
Alpina	D4	09/2020-06/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D4	09/2020-06/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Alpina	D4	09/2020-06/2026	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
Alpina	D4	03/2014-07/2020	433MHz		●	●	○	A	433MHz	Continental	●	●
Alpina	D5	11/2021-06/2024	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	D5	01/2017-06/2024	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	D5	03/2014-12/2016	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D5	09/2011-12/2014	433MHz 36236798726		●	●	○	0*/A	433MHz	Huf/Beru	●	●
Alpina	D5	02/2010-02/2014	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
Alpina	XB7	07/2022-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Alpina	XB7	07/2022-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	XB7	01/2020-06/2022	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	XB7	01/2020-06/2022	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	XD3	08/2017-06/2024	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	XD3	08/2017-06/2024	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	XD3	04/2014-06/2017	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
Alpina	XD3	09/2010-03/2014	433MHz	F25	●	●	○	0*/A	433MHz	Huf/Beru	●	●
Alpina	XD3	09/2010-02/2014	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	XD4	09/2018-06/2024	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	XD4	01/2018-06/2024	315MHz		●	●	○	A	315MHz	Schrader	●	●
Aston Martin	DB11	01/2017-12/2019	315MHz		●	●	○	A	315MHz	Schrader	●	●
Aston Martin	DB12	01/2024-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	DB9	01/2010-12/2015	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Aston Martin	DBS	01/2008-12/2008	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Aston Martin	DBX	10/2020-12/2026	433MHz		●	●	○	A	433MHz	Schrader	●	●
Aston Martin	DBX	04/2020-12/2026	433MHz Huf		●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Rapide	01/2011-12/2019	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Aston Martin	Vanquish	01/2025-12/2026	433MHz A0009054104		●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vanquish	01/2013-12/2018	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Aston Martin	Vantage	07/2005-12/2026	433MHz	AM305	●	●	○	A	433MHz	Huf/Beru	●	●
Audi	A6	01/2019-12/2023	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	A7	01/2019-12/2023	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	A8	01/2003-12/2023	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	A8	10/2002-12/2012	433MHz	4E	●	●	○	0/A	433MHz	Huf/Beru	●	●
Audi	Q2	01/2017-12/2023	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Audi	Q7	01/2017-12/2017	433MHz	4L/AU726	●	●	○	0/A	433MHz	Huf/Beru	●	●
Audi	Q7	01/2016-12/2023	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	Q7	01/2007-12/2015	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●

Audi	R8	01/2007-12/2022	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	RS Q3	01/2018-12/2023	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Audi	RS4	01/2019-12/2020	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	RS6	01/2013-12/2018	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	RS7	01/2013-12/2018	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	S8	01/2010-12/2017	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Audi	S8	10/2002-10/2009	433MHz	D3	●	●	○	A	433MHz	Huf/Beru	●	●
Bentley	Continental GT	01/2009-01/2014	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
Bentley	Continental GTC	01/2025-12/2026	315MHz 95C907275A		●	●	○	0/A	315MHz	BHSENS	●	●
Bentley	Flying Spur	01/2011-12/2015	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Bentley	Flying Spur	01/2005-12/2010	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Bentley	Mulsanne	01/2012-12/2012	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
BMW	1 Series	07/2019-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	1 Series	07/2019-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	1 Series	03/2014-12/2018	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	1 Series	01/2014-12/2024	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	1 Series	09/2010-12/2013	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	1 Series	01/2007-08/2010	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	2 Series	11/2019-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	2 Series	11/2019-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	2 Series	03/2014-12/2024	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	2 Series	11/2012-02/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	3 Series	03/2019-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	03/2019-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	3 Series	03/2019-12/2026	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	3 Series	03/2019-12/2026	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	3 Series	03/2014-12/2022	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	3 Series	10/2010-03/2014	433MHz	F30/F31/F34	●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	3 Series	09/2009-12/2013	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	3 Series	01/2005-08/2009	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	3 Series	03/1999-12/2013	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	3 Series	01/1999-12/2002	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	3 Series	01/1998-12/2003	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	4 Series	07/2020-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	4 Series	07/2020-12/2026	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	4 Series	07/2020-12/2026	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	4 Series	07/2013-12/2021	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	5 Series	07/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	5 Series	07/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	5 Series	11/2016-12/2024	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	5 Series	11/2016-12/2024	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	5 Series	03/2014-12/2017	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●

BMW	5 Series	09/2010-02/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	5 Series	05/2003-12/2013	433MHz 36236798726		●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	5 Series	08/1998-05/2004	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	6 Series	04/2014-12/2018	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	6 Series	01/2011-03/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	6 Series	08/2003-10/2012	433MHz	E63/E64	●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	6 Series GT	07/2017-12/2024	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	6 Series GT	07/2017-12/2024	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	7 Series	07/2022-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	7 Series	07/2022-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	7 Series	06/2015-12/2022	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	7 Series	06/2015-12/2022	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	7 Series	03/2014-05/2015	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	7 Series	09/2010-02/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	7 Series	01/2006-08/2010	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	7 Series	01/2002-12/2005	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	8 Series	07/2018-12/2026	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	8 Series	07/2018-12/2026	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	i3	01/2022-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	i3	01/2013-06/2022	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	i4	01/2021-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	i4	01/2021-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	i5	07/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	i5	07/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	i7	07/2022-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	i7	07/2022-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	i8	01/2013-12/2022	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	iX	01/2021-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	iX	01/2021-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	iX1	11/2022-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	iX1	11/2022-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	iX2	11/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	iX2	11/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	iX3	01/2026-12/2026	315MHz		○	●	○	A	315MHz	Schrader	●	●
BMW	iX3	01/2026-12/2026	433MHz		○	●	○	A	433MHz	Schrader	●	●
BMW	iX3	08/2017-12/2025	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	iX3	08/2017-12/2025	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	M2	12/2022-12/2026	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	M2	12/2022-12/2026	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	M2	11/2014-12/2021	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	M3	11/2020-12/2026	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	M3	11/2020-12/2026	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	M3	01/2014-12/2019	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	M4	07/2021-12/2026	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	M4	07/2021-12/2026	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	M4	03/2014-12/2021	433MHz Continental		●	●	○	A	433MHz	Continental	●	●

BMW	M5	11/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	M5	11/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	M5	03/2014-12/2017	433MHz 36106874830		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	M5	09/2010-03/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	M6	03/2014-12/2018	433MHz	F12	●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	M6	06/2011-12/2015	433MHz 36106856227		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	M8	01/2019-12/2025	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	Motorcycle	01/2010-12/2019	433MHz		○	○	○		433MHz	Schrader	Activate Only	●
BMW	X1	11/2022-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X1	11/2022-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X1	08/2015-12/2023	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	X1	03/2014-12/2016	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X1	09/2008-02/2014	433MHz	E84	●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X2	11/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X2	11/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X2	01/2016-12/2023	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	X3	11/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X3	11/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X3	01/2017-12/2025	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	X3	01/2017-12/2025	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	X3	04/2014-12/2017	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X3	11/2010-03/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X3	03/2003-07/2011	433MHz	E83	●	●	○	0*/A	433MHz	Huf/Beru	●	●
BMW	X4	04/2018-06/2026	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	X4	04/2018-06/2026	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	X4	01/2014-12/2018	433MHz 36106790054		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X4	05/2013-03/2018	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X5	04/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X5	04/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X5	08/2018-03/2023	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	X5	08/2018-03/2023	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	X5	08/2013-12/2018	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	X5	10/2010-06/2013	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X5	11/2006-09/2010	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X5	10/1999-09/2007	433MHz	E53	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X6	01/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X6	01/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X6	08/2019-12/2023	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	X6	08/2019-12/2023	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	X6	08/2014-07/2019	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	X6	10/2010-07/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X6	12/2007-09/2010	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●

BMW	X7	08/2022-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X7	08/2022-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X7	12/2018-07/2022	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	X7	12/2018-07/2022	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	XM	12/2022-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	XM	12/2022-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	Z4	11/2018-06/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	Z4	11/2018-06/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	Z4	03/2014-12/2016	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	Z4	01/2006-02/2014	433MHz 36106790054		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	Z4	10/2002-12/2011	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
BYD	ATTO 1	01/2025-12/2026	433MHz EUEA3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	ATTO 1	04/2023-12/2026	433MHz		●	●	○	0	433MHz	Schrader	●	●
BYD	ATTO 2	10/2025-12/2026	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	ATTO 3	10/2025-12/2026	433MHz SA3HE3609200G		●	●	○	0	433MHz	BHSENS	●	●
BYD	ATTO 3	10/2025-06/2026	433MHz SA3HE3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	ATTO 3	01/2025-12/2026	433MHz EUEA3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	ATTO 3	01/2025-06/2026	433MHz SA3HE3609200E		●	●	○	0	433MHz	SAT	●	●
BYD	ATTO 3	02/2022-02/2025	433MHz		●	●	○	0/A	433MHz	BHSENS	●	●
BYD	ATTO 3	12/2021-06/2025	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	ATTO 3	12/2021-02/2025	433MHz SC3609200		●	●	○	0	433MHz	Schrader	●	●
BYD	DOLPHIN	01/2025-12/2026	433MHz EUEA3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	DOLPHIN	01/2025-12/2026	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	DOLPHIN	12/2022-12/2024	433MHz SC3609200H		●	●	○	0	433MHz	Schrader	●	●
BYD	DOLPHIN	12/2022-12/2024	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	DOLPHIN	08/2021-02/2025	433MHz		●	●	○	0/A	433MHz	Baolong	●	●
BYD	DOLPHIN	08/2021-12/2024	433MHz SC3609200		●	●	○	0	433MHz	Schrader	●	●
BYD	DOLPHIN	08/2021-12/2024	433MHz SC3609200C		●	●	○	0	433MHz	YunLing	●	●
BYD	DOLPHIN MINI	01/2025-12/2026	433MHz EUEA3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	DOLPHIN MINI	04/2023-12/2026	433MHz		●	●	○	0	433MHz	Schrader	●	●
BYD	DOLPHIN SURF	01/2025-12/2026	433MHz EUEA3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	DOLPHIN SURF	04/2023-12/2026	433MHz		●	●	○	0	433MHz	Schrader	●	●
BYD	Seagull	04/2023-12/2026	433MHz SA3HE3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	Seagull	04/2023-06/2026	433MHz		●	●	○	0	433MHz	Schrader	●	●
BYD	SEAL DM-i	09/2023-12/2024	433MHz		●	●	○	0	433MHz	BHSENS	●	●
BYD	SEAL DM-i	09/2023-12/2024	433MHz SC3609200		●	●	○	0	433MHz	Schrader	●	●
BYD	SEAL EV	08/2024-12/2026	433MHz		●	●	○	A/0	433MHz	BHSENS	●	●
BYD	SEAL EV	08/2024-12/2026	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	SEAL EV	08/2024-02/2025	433MHz SC3609200		●	●	○	0	433MHz	Schrader	●	●

BYD	SEAL EV	08/2024-02/2025	433MHz SA3HE3609200B		●	●	○	0/A	433MHz	BHSENS	●	●
BYD	SEAL EV	07/2022-07/2024	433MHz SC3609200		●	●	○	0	433MHz	Schrader	●	●
BYD	SEAL EV	07/2022-07/2024	433MHz SA3HE3609200B		●	●	○	0/A	433MHz	BHSENS	●	●
BYD	SEAL EV	07/2022-07/2024	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	SEALION 6	01/2026-12/2026	433MHz		●	●	○	0	433MHz	BHSENS	●	●
BYD	SEALION 6	07/2024-12/2026	433MHz EUEA3609200C		●	●	○	0	433MHz	WILLING	●	●
BYD	SEALION 6	07/2024-12/2026	433MHz EUEA3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	SEALION 7 EV	05/2024-12/2026	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	YUAN PLUS	01/2026-06/2026	433MHz		●	●	○	0	433MHz	Schrader	●	●
BYD	YUAN PLUS	10/2025-12/2026	433MHz SA3HE3609200G		●	●	○	0	433MHz	BHSENS	●	●
BYD	YUAN PLUS	10/2025-06/2026	433MHz SA3HE3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	YUAN PLUS	01/2025-12/2026	433MHz EUEA3609200B		●	●	○	0	433MHz	BHSENS	●	●
BYD	YUAN PLUS	01/2025-06/2026	433MHz SA3HE3609200E		●	●	○	0	433MHz	SAT	●	●
BYD	YUAN PLUS	02/2022-02/2025	433MHz		●	●	○	0/A	433MHz	BHSENS	●	●
BYD	YUAN PLUS	12/2021-06/2025	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	YUAN PLUS	12/2021-02/2025	433MHz SC3609200		●	●	○	0	433MHz	Schrader	●	●
BYD	YUAN UP	10/2025-12/2026	315MHz		●	●	○	0	315MHz	BHSENS	●	●
Cadillac	ATS	07/2017-12/2019	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	ATS	07/2017-12/2019	315MHz 13598786		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	ATS	07/2017-12/2019	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	ATS	07/2015-12/2017	315MHz 13598786		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	ATS	07/2015-12/2017	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	ATS	07/2015-12/2017	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	ATS	07/2012-12/2015	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	CT6	07/2018-12/2020	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CT6	07/2016-12/2021	433MHz 13598773		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	CT6	07/2016-12/2018	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CT6	01/2016-12/2016	433MHz 13598773		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	CT6	01/2016-12/2016	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	07/2017-12/2019	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	07/2017-12/2019	433MHz 13598787		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	CTS	01/2016-12/2017	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	07/2015-12/2017	433MHz 13598787		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	CTS	09/2013-12/2015	433MHz 20925925		●	●	●	0/S	433MHz	Schrader	●	●

Cadillac	CTS	09/2013-12/2014	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	09/2013-12/2014	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	07/2008-12/2013	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	07/2008-12/2013	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	07/2008-12/2013	433MHz 20925925		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	CTS	01/2007-12/2008	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	CTS	07/2003-12/2007	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
Cadillac	DTS	01/2009-12/2011	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	DTS	07/2007-12/2008	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	DTS	07/2005-12/2007	315MHz 25920615		○	●	○	S	315MHz	Schrader	●	●
Cadillac	Escalade	09/2020-12/2026	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Cadillac	Escalade	09/2020-12/2026	433MHz 13538761		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	Escalade	09/2020-12/2023	433MHz 13540603		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	Escalade	06/2017-12/2020	433MHz 13528563		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	Lyriq	07/2024-12/2026	315MHz 13549918		●	●	○	0/S	315MHz	Schrader	●	●
Cadillac	Lyriq	07/2023-12/2026	315MHz		●	●	○	A/0/S	315MHz	Schrader	●	●
Cadillac	Lyriq	06/2022-12/2026	433MHz 13530661		●	●	○	A/0/S	433MHz	Schrader	●	●
Cadillac	XT5	07/2016-12/2021	433MHz 13516165		●	●	●	0/S	433MHz	Schrader	●	●
Cadillac	XT5	07/2016-12/2021	315MHz 13516164		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Camaro	07/2019-12/2024	315MHz		●	●	●	0	315MHz	Schrader	●	●
Chevrolet	Camaro	07/2019-12/2024	433MHz Clamp in		●	●	●	0/S	433MHz	Schrader	●	●
Chevrolet	Camaro	07/2019-12/2024	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Chevrolet	Camaro	07/2016-12/2024	433MHz 13516165		●	●	●	0/S	433MHz	Schrader	●	●
Chevrolet	Camaro	07/2016-12/2019	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Camaro	07/2016-12/2019	315MHz 13598786		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Camaro	07/2013-12/2015	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Chevrolet	Camaro	07/2011-12/2016	315MHz 20964159		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Camaro	07/2010-12/2016	433MHz Snap in		●	●	●	0/S	433MHz	Schrader	●	●
Chevrolet	Camaro	01/2009-12/2016	315MHz 22854866		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Captiva	07/2012-12/2018	433MHz 25789964		●	●	●	0/S	433MHz	Schrader	●	●
Chevrolet	Captiva	07/2011-12/2018	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Corvette	07/2020-12/2026	433MHz 13554170		●	●	○	0/S/A	433MHz	Schrader	●	●
Chevrolet	Corvette	07/2020-12/2025	315MHz 13538759		●	●	○	0/S/A	315MHz	Schrader	●	●

Chevrolet	Corvette	07/2018-12/2019	315MHz 13581559		●	●	●	0/S/A	315MHz	Schrader	●	●
Chevrolet	Corvette	07/2013-12/2018	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Corvette	07/2009-12/2013	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
Chevrolet	Corvette	01/2005-12/2009	315MHz 25758220		●	●	○	0/S	315MHz	Schrader	●	●
Chevrolet	HHR	07/2008-12/2011	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	HHR	07/2008-12/2010	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	HHR	07/2007-12/2008	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	HHR	06/2007-12/2008	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Sonic	07/2014-12/2020	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Chevrolet	Sonic	07/2011-12/2014	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Chrysler	300	01/2010-12/2015	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300	01/2009-12/2009	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300	01/2008-12/2008	433MHz		●	●	●	0/A	433MHz	Continental	●	●
Chrysler	300	01/2005-12/2007	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Chrysler	300C	06/2009-12/2017	433MHz 18 inch		●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300C	06/2009-12/2017	433MHz 20 inch		●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300C	06/2005-05/2009	433MHz		●	●	●	0/A	433MHz	Continental	●	●
Chrysler	300M	01/2002-12/2004	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
Chrysler	Crossfire	01/2003-12/2008	433MHz		●	●	○	A	433MHz	Schrader	●	●
Chrysler	PT Cruiser	08/2007-12/2010	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Chrysler	Ypsilon	04/2011-12/2017	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Citroen	Berlingo	07/2018-12/2025	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	C3	09/2009-12/2024	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Citroen	C4	10/2014-10/2018	433MHz	B58	●	●	○	0/A	433MHz	Schrader	●	●
Citroen	C4	08/2010-12/2024	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	C4	08/2008-09/2014	433MHz		●	●	○	0	433MHz	Schrader	●	●
Citroen	C4	09/2004-07/2008	433MHz	B5	●	●	○	0	433MHz	Continental	●	●
Citroen	C4 Cactus	05/2014-04/2021	433MHz		○	●	○	A	433MHz	Schrader	●	●
Citroen	C4 Picasso	05/2006-02/2013	433MHz		●	●	○	0	433MHz	Schrader	●	●
Citroen	C5	09/2013-12/2020	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Citroen	C5	08/2004-08/2013	433MHz	X3/X40	●	●	○	0	433MHz	Continental	●	●
Citroen	C5	12/2000-07/2004	433MHz	X40	●	●	○	0	433MHz	Schrader	●	●
Citroen	C5 Aircross	09/2017-12/2025	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Citroen	C6	01/2005-12/2013	433MHz	X6	●	●	○	0	433MHz	Continental	●	●
Citroen	DS3	01/2009-12/2019	433MHz		○	●	○	C	433MHz	Schrader	●	●
Citroen	DS4	02/2014-07/2020	433MHz	B81	●	●	○	0/A	433MHz	Schrader	●	●
Citroen	DS4	12/2010-01/2014	433MHz	B75	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS5	02/2014-11/2018	433MHz	X2/50	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS5	06/2011-01/2014	433MHz	B81	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS7	01/2018-12/2024	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS7	03/2017-12/2021	433MHz		●	●	○	0	433MHz	Schrader	●	●
Daewoo	Matiz Kasten	01/2000-12/2014	433MHz		○	●	○	C	433MHz	Schrader	●	●
Daihatsu	ACTIS	01/2017-12/2017	315MHz		○	●	○	C	315MHz	Pacific	●	●
Dodge	Avenger	01/2007-12/2014	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Dodge	Avenger	01/2007-12/2010	433MHz		●	●	●	0/A	433MHz	Continental	●	●

Dodge	Caliber	01/2007-12/2012	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Dodge	Caliber	01/2006-12/2012	433MHz		●	●	●	0	433MHz	Schrader	●	●
Dodge	Nitro	01/2009-12/2012	315MHz		●	●	●	0/A	315MHz	Schrader	●	●
Dodge	Nitro	11/2006-12/2008	315MHz		●	●	●	0/A	315MHz	Schrader	●	●
Dodge	Nitro	06/2006-12/2012	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Ferrari	12 Cilindri Spider	06/2024-12/2026	315MHz		○	●	○	A	315MHz	BHSENS	●	●
Ferrari	296 GTS	06/2022-12/2026	315MHz		○	●	○	A	315MHz	BHSENS	●	●
Ferrari	296GTB	01/2022-12/2022	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	296GTB	01/2021-12/2024	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	458 Italia	01/2014-12/2015	315MHz 290569		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	458 Italia	01/2011-12/2017	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	458 Italia	01/2009-12/2013	315MHz 249363		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	458 Speciale	01/2013-12/2015	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	458 Speciale Aperta	01/2013-12/2015	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	458 Spider	01/2011-12/2019	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	488	01/2015-12/2019	315MHz 290569		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	488	01/2015-12/2017	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	488 GTB	01/2015-12/2019	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	488 Pista	01/2016-12/2019	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	488 Pista Spider	01/2016-12/2019	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	488 Spider	01/2015-12/2019	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	575M Maranello	01/2002-12/2006	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	599 GTB	01/2006-12/2012	315MHz	F141	●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	599 GT0	01/2006-12/2012	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	599 SA Aperta	01/2010-12/2010	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	612 Scaglietti	01/2004-12/2011	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	612 Sessanta	01/2007-12/2007	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	812 GTS	01/2017-12/2025	315MHz		●	●	○	A	315MHz	Huf	●	●
Ferrari	812 Superfast	01/2017-12/2024	315MHz 314821		●	●	○	A	315MHz	Huf	●	●
Ferrari	812 Superfast	01/2017-12/2017	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	California	10/2008-12/2017	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	California	10/2008-12/2017	315MHz 249363		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	Daytona SP3	01/2022-12/2023	315MHz		○	●	○	A	315MHz	Huf	●	●
Ferrari	Enzo	01/2003-12/2004	315MHz	F140	●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	F12 Berlinetta	10/2012-12/2016	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	F12 Berlinetta	10/2012-12/2014	315MHz 290569		●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	F12 tdf	01/2016-12/2017	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	F12 tdf	01/2015-12/2021	315MHz 290569		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	F430	01/2005-12/2009	315MHz	F131E	●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	F8 Spider	01/2021-12/2023	315MHz		●	●	○	A	315MHz	Huf	●	●
Ferrari	F8 Tributo	04/2019-12/2023	315MHz		●	●	○	A	315MHz	Huf	●	●
Ferrari	FF	01/2011-06/2019	315MHz	F151	●	●	○	0/A	315MHz	Huf/Beru	●	●
Ferrari	GTC4 Lusso	01/2016-12/2020	315MHz 314821		●	●	○	A	315MHz	Huf	●	●
Ferrari	GTC4 Lusso	01/2016-12/2017	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	GTC4 Lusso T	01/2017-12/2021	315MHz		●	●	○	A	315MHz	Huf	●	●
Ferrari	La Ferrari	01/2013-12/2020	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●

Ferrari	Portofino	01/2017-12/2017	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Ferrari	Portofino	01/2016-12/2023	315MHz 314821		●	●	○	A	315MHz	Huf	●	●
Ferrari	Purosangue	01/2022-12/2026	315MHz		○	●	○	A	315MHz	BHSENS	●	●
Ferrari	Roma	01/2020-12/2026	315MHz		○	●	○	A	315MHz	Huf	●	●
Ferrari	Roma Spider	01/2023-12/2026	315MHz		○	●	○	A	315MHz	Huf	●	●
Ferrari	SF90	01/2020-12/2025	315MHz		○	●	○	A	315MHz	Huf	●	●
Ferrari	SF90 Spider	01/2020-12/2025	315MHz		○	●	○	A	315MHz	Huf	●	●
Ferrari	SF90 Stradale	01/2020-12/2026	315MHz		○	●	○	A	315MHz	Huf	●	●
Ferrari	SF90 xx Spider	01/2023-12/2026	315MHz		○	●	○	A	315MHz	Huf	●	●
Fiat	500	01/2014-12/2024	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	Panda	01/2012-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Ford	Ecosport	09/2017-12/2023	433MHz		●	●	○	O/S	433MHz	Schrader	●	●
Ford	Ecosport	07/2017-12/2023	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Ford	Ecosport	06/2015-06/2017	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Ford	Ecosport	10/2014-08/2017	433MHz		●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Ecosport	06/2013-09/2014	433MHz		●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Expedition	03/2002-12/2004	433MHz		●	●	○	S	433MHz	Schrader	●	●
Ford	Explorer	01/2018-12/2019	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Ford	Explorer	01/2018-12/2019	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Ford	Explorer	01/2016-12/2017	433MHz		●	●	○	O/S	433MHz	Schrader	●	●
Ford	Explorer	01/2016-12/2017	315MHz F2GZ1A189A		●	●	○	O/S	315MHz	Schrader	●	●
Ford	Explorer	05/2015-12/2015	433MHz F2GZ1A189B		●	●	●	S	433MHz	Schrader	●	●
Ford	Explorer	05/2015-12/2015	315MHz		●	●	●	S	315MHz	Schrader	●	●
Ford	Explorer	11/2010-12/2015	315MHz Schrader		●	●	●	S	315MHz	Schrader	●	●
Ford	Explorer	11/2010-05/2015	433MHz BB5Z1A189A		●	●	●	S	433MHz	Schrader	●	●
Ford	Fiesta	05/2014-08/2019	433MHz		●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Focus	01/2014-12/2016	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Ford	Focus	01/2013-12/2013	433MHz		●	●	●	S	433MHz	Schrader	●	●
Ford	Kuga	01/2014-12/2019	433MHz		●	●	●	O/S/A	433MHz	Schrader	●	●
Ford	Mustang	01/2024-12/2026	433MHz		●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Mustang	01/2024-12/2026	433MHz PR3Z1A189M		●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Mustang	01/2020-12/2026	315MHz		●	●	○	O/S/A	315MHz	Schrader	●	●
Ford	Mustang	01/2020-12/2023	433MHz		●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Mustang	07/2014-12/2019	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Ford	Mustang	07/2014-12/2019	433MHz		●	●	●	O/S/A	433MHz	Schrader	●	●
Ford	Mustang	01/2010-06/2014	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Ford	Mustang Mach-E	07/2024-12/2026	433MHz PR3Z1A189M		●	●	○	O/S/A	433MHz	Schrader	●	●
Honda	Honda e	01/2019-12/2023	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	Legend	01/2015-12/2021	315MHz	Hybrid	●	●	○	0	315MHz	TRW	●	●
Honda	NSX	01/2016-06/2021	433MHz		●	●	○	0	433MHz	Continental	●	●
Honda	NSX	01/2016-12/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	Odyssey	01/2021-06/2025	433MHz 42753T3RA02		●	●	○	0	433MHz	Continental	●	●
Honda	Odyssey	01/2017-12/2023	433MHz 42753T6NA01		●	●	○	0	433MHz	Continental	●	●
Honda	Odyssey	01/2014-12/2016	433MHz		●	●	○	0	433MHz	TRW	●	●

Honda	ZR-V	01/2023-12/2023	Indirect		○	○	○	A	N/A	N/A	Indirect	●
HongQi	H9	04/2024-06/2026	433MHz 3778080DB01B		●	●	○	0	433MHz	Baolong	●	●
HongQi	H9	08/2020-12/2024	433MHz		●	●	○	0	433MHz	Baolong	●	●
HongQi	H9	06/2020-12/2022	433MHz 3778080CF41A		●	●	○	0	433MHz	Baolong	●	●
HongQi	HS5	05/2023-06/2025	433MHz 3778080DB01A		●	●	○	0	433MHz	Baolong	●	●
Hyundai	Elantra N	01/2022-12/2026	433MHz 52940L8200		●	●	○	0/A	433MHz	Schrader	●	●
Hyundai	Elantra N	01/2022-12/2026	433MHz 52940CG100		●	●	○	0/A	433MHz	Schrader	●	●
Hyundai	Genesis Coupe	01/2011-12/2016	315MHz Hi Line	BK	●	●	○	0	315MHz	Continental	●	●
Hyundai	Genesis Coupe	01/2008-12/2012	315MHz Lo Line	BK	●	●	○	0	315MHz	Continental	●	●
Hyundai	i30	01/2007-12/2016	433MHz	FD/Fde	●	●	○	0	433MHz	Continental	●	●
Hyundai	Ioniq 5	01/2025-12/2025	433MHz 52940L1100	NEG\Nei EV	●	●	○	0	433MHz	Continental	●	●
Hyundai	Ioniq 5	01/2022-12/2022	433MHz 52933D4100		●	●	○	0	433MHz	Continental	●	●
Hyundai	Ioniq 5	10/2021-12/2024	433MHz 52940L1100		●	●	○	0/A	433MHz	Continental	●	●
Hyundai	Ioniq 5	10/2021-12/2024	433MHz 52940L8200		●	●	○	0/A	433MHz	Schrader	●	●
Hyundai	Ioniq 6	01/2021-12/2026	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Hyundai	Kona	01/2023-12/2026	433MHz	SX2	●	●	○	A/0	433MHz	Continental	●	●
Hyundai	Kona	01/2023-12/2026	433MHz 52940BE000	SX2	●	●	○	A/0	433MHz	Continental	●	●
Hyundai	Kona	01/2017-12/2023	433MHz	OS	●	●	○	A/0	433MHz	Continental	●	●
Hyundai	Kona electric	01/2024-12/2026	433MHz	SX2 EV	●	●	○	A/0	433MHz	Continental	●	●
Hyundai	Kona electric	07/2023-12/2026	433MHz 52940BE000	SX2 EV	●	●	○	A/0	433MHz	Continental	●	●
Hyundai	Kona electric	01/2023-12/2026	315MHz 529333N000	SX2 EV	●	●	○	A/0	315MHz	Continental	●	●
Hyundai	Kona electric	01/2017-12/2024	433MHz	OS EV	●	●	○	A/0	433MHz	Continental	●	●
Hyundai	Kona N	01/2022-12/2026	433MHz	OSN	●	●	○	A/0	433MHz	Continental	●	●
Hyundai	Nexo	08/2024-12/2025	433MHz 52940E2100	FE	●	●	○	0/A	433MHz	Schrader	●	●
Hyundai	Nexo	01/2020-12/2025	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Hyundai	Nexo	04/2018-12/2025	433MHz	FE	●	●	○	0/A	433MHz	Schrader	●	●
Jaguar	E-Pace	01/2022-12/2026	433MHz M8E21A159AA	X540	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	E-Pace	01/2019-12/2022	433MHz	X540	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	E-Pace	01/2017-12/2018	433MHz	X540	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Pace	01/2022-12/2026	433MHz M8E21A159AA	X761	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Pace	01/2019-12/2022	433MHz	X761	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Pace	01/2015-12/2018	433MHz	X761	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	01/2021-12/2023	433MHz M8E21A159AA	X152	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	01/2019-12/2026	433MHz GX631A159AA	X152	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	01/2019-06/2021	433MHz FW931A159AB	X152	●	●	○	0/A	433MHz	Continental	●	●

Jaguar	F-Type	05/2016-12/2018	433MHz FW931A159AB	X152	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	05/2016-12/2018	433MHz GX631A159AA	X152	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	11/2012-04/2016	315MHz AH521A159CA	X152	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	F-Type	11/2012-04/2016	433MHz FW931A159AB	X152	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	11/2012-04/2016	433MHz AH521A159AA	X152	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	I-Pace	01/2021-12/2026	433MHz M8E21A159AA	X590	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	I-Pace	01/2019-12/2023	433MHz GX631A159AA	X590	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	S-Type	10/1998-08/2011	315MHz	X200	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	S-Type	10/1998-08/2011	433MHz	X200	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	X-Type	01/2001-12/2009	315MHz	X400	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	X-Type	01/2001-12/2009	433MHz	X400	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XE	01/2022-12/2026	433MHz M8E21A159AA	X760	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XE	01/2018-12/2022	433MHz GX631A159AA	X760	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XE	01/2016-12/2017	433MHz GX631A159AA	X760	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XE	04/2015-12/2016	433MHz FW931A159AB	X760	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XF	01/2019-12/2026	433MHz GX631A159AA	X260	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XF	09/2015-12/2018	433MHz	X260	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XF	04/2009-08/2015	315MHz	X250	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	XF	01/2008-12/2017	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Jaguar	XF	01/2007-08/2015	433MHz	X250	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	01/2016-04/2020	433MHz GX631A159AA	X351	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	01/2015-12/2015	433MHz FW931A159AB	X351	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	01/2010-12/2015	433MHz AH521A159AA	X351	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	01/2010-12/2015	315MHz AH521A159CA	X351	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	XJ	01/2010-12/2012	433MHz BH521A159AA	X351	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	01/2010-12/2012	315MHz BH521A159CA	X351	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	XJ	12/2002-12/2009	433MHz	X350	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	12/2002-12/2009	315MHz	X350	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	XK	01/2010-12/2015	315MHz	X150	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	XK	01/2010-12/2015	433MHz	X150	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XK	01/2006-12/2009	433MHz	X150	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XK	01/2006-12/2009	315MHz	X150	●	●	○	0/A	315MHz	Continental	●	●
Jeep	Avenger	01/2023-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Jeep	Cherokee	01/2019-12/2023	433MHz		●	●	○	0/A	433MHz	TRW	●	●
Jeep	Cherokee	01/2019-12/2022	315MHz		●	●	○	0/A	315MHz	TRW	●	●
Jeep	Cherokee	01/2018-12/2018	433MHz		●	●	○	0/A	433MHz	TRW	●	●
Jeep	Cherokee	01/2018-12/2018	315MHz		●	●	○	0/A	315MHz	TRW	●	●

Jeep	Cherokee	01/2016-12/2017	433MHz		●	●	●	0/A	433MHz	TRW	●	●
Jeep	Cherokee	01/2013-12/2017	315MHz		●	●	●	0/A	315MHz	TRW	●	●
Jeep	Cherokee	01/2013-12/2015	433MHz		●	●	●	0/A	433MHz	TRW	●	●
Jeep	Commander	01/2022-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Jeep	Commander	01/2021-12/2026	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jeep	Commander	01/2008-12/2010	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Commander	01/2006-12/2007	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Jeep	Compass	01/2019-12/2026	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jeep	Compass	01/2019-12/2026	315MHz Continental		●	●	○	0/A	315MHz	Continental	●	●
Jeep	Compass	01/2013-12/2014	315MHz		●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Compass	01/2010-12/2015	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Gladiator	01/2023-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Jeep	Gladiator	01/2021-12/2026	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jeep	Grand Cherokee	11/2023-12/2026	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Jeep	Grand Cherokee	01/2023-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Jeep	Grand Cherokee	01/2021-12/2026	433MHz Conti		●	●	○	0/A	433MHz	Continental	●	●
Jeep	Grand Cherokee	06/2006-12/2010	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Grand Cherokee	01/2006-12/2007	315MHz		●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Grand Cherokee	01/2005-12/2007	433MHz Conti		●	●	●	0/A	433MHz	Continental	●	●
Jeep	Grand Cherokee	05/2004-12/2005	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Jeep	Patriot	01/2013-12/2017	315MHz		●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Patriot	01/2006-12/2012	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Jeep	Renegade	01/2018-12/2026	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jeep	Renegade	01/2018-12/2025	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Jeep	Renegade	01/2016-12/2017	433MHz 68252493AB		●	●	●	0/A	433MHz	Continental	●	●
Jeep	Renegade	07/2014-12/2017	433MHz		●	●	●	0/A	433MHz	Continental	●	●
Jeep	Renegade	07/2014-12/2017	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Jeep	Wrangler	01/2022-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Jeep	Wrangler	07/2021-12/2026	433MHz Conti		●	●	○	0/A	433MHz	Continental	●	●
Jeep	Wrangler	01/2021-12/2022	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Jeep	Wrangler	01/2018-12/2019	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Jeep	Wrangler	01/2015-12/2017	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Wrangler	01/2013-12/2014	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Wrangler	01/2010-12/2012	315MHz		●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Wrangler	01/2010-12/2012	433MHz Snap in		●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Wrangler	01/2007-12/2010	315MHz Clamp in		●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Wrangler	06/2006-12/2010	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
KIA	PV5	01/2025-12/2026	433MHz 52940E2100		●	●	○	0	433MHz	Schrader	●	●
Lamborghini	Aventador	01/2011-12/2012	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
Lamborghini	Huracan	01/2015-12/2016	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
Lamborghini	Urus	01/2019-12/2024	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●

Land Rover	Defender	01/2020-12/2026	433MHz M8E21A159AA	L663	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Defender	01/2020-12/2023	433MHz GX631A159AA	L663	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Defender	01/2020-12/2023	433MHz FW931A159AB	L663	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Defender	01/1997-12/2019	433MHz BH521A159AA	L316	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery	01/2021-12/2026	433MHz M8E21A159AA	L462	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery	01/2017-12/2022	433MHz GX631A159AA	L462	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery	12/2009-12/2016	433MHz FW931A159AB	L319	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery	12/2009-12/2016	433MHz AH521A159AA	L319	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery	12/2009-12/2016	315MHz BH521A159CA	L319	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Discovery	12/2009-12/2016	433MHz BH521A159AA	L319	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery	12/2009-12/2016	433MHz GX631A159AA	L319	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery	12/2009-12/2016	315MHz AH521A159CA	L319	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Discovery	06/2004-11/2009	433MHz	L319	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery	06/2004-11/2009	315MHz	L319	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Discovery	01/2002-05/2004	433MHz	L318	●	●	○	0/A	433MHz	Huf/Beru	●	●
Land Rover	Discovery Sport	01/2021-12/2026	433MHz M8E21A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery Sport	01/2019-12/2022	433MHz GX631A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery Sport	01/2019-12/2022	433MHz BH521A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery Sport	01/2015-12/2016	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Discovery Sport	06/2014-12/2018	433MHz FW931A159AB	L550	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery Sport	06/2014-12/2018	433MHz GX631A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Discovery Sport	01/2014-12/2018	433MHz BH521A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	FreeLander	01/2006-12/2014	433MHz FW931A159AB	L359	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	FreeLander	01/2006-12/2014	315MHz 4H231A159CA	L359	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	FreeLander	01/2006-12/2014	315MHz AH521A159CA	L359	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	FreeLander	01/2006-12/2014	433MHz BH521A159AA	L359	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	FreeLander	01/2006-12/2014	433MHz GX631A159AA	L359	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	FreeLander	01/2006-12/2014	315MHz BH521A159CA	L359	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover	01/2026-12/2026	433MHz M8E21A159AA	L460	●	●	○	A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2022-12/2025	433MHz M8E21A159AA	L460	●	●	○	0/A	433MHz	Continental	●	●

Land Rover	Range Rover	01/2022-12/2023	433MHz GX631A159AA	L460	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	02/2020-12/2021	433MHz M8E21A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2017-12/2021	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2016-12/2016	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2016-12/2016	433MHz FW931A159AB	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2013-12/2015	433MHz FW931A159AB	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2013-12/2015	315MHz AH521A159CA	L405	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover	01/2013-12/2015	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2013-12/2015	433MHz AH521A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2010-12/2012	315MHz BH521A159CA	L322	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover	01/2010-12/2012	433MHz BH521A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2010-12/2012	433MHz GX631A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2010-12/2012	433MHz AH521A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2010-12/2012	315MHz AH521A159CA	L322	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover	01/2005-12/2009	315MHz	L322	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover	01/2005-12/2009	433MHz	L322	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover	01/2002-12/2004	433MHz	L322	●	●	○	0/A	433MHz	Huf/Beru	●	●
Land Rover	Range Rover Evoque	07/2021-12/2026	433MHz M8E21A159AA	L551	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Evoque	01/2019-12/2023	433MHz GX631A159AA	L551	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2015-12/2018	433MHz GX631A159AA	L538	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2015-12/2018	433MHz BH521A159AA	L538	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2015-12/2018	315MHz BH521A159CA	L538	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2015-12/2017	433MHz FW931A159AB	L538	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Evoque	01/2012-12/2014	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2011-12/2016	433MHz AH521A159AA	L538	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2011-06/2015	433MHz BH521A159AA	L538	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2011-06/2015	315MHz AH521A159CA	L538	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2011-06/2015	315MHz BH521A159CA	L538	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Evoque	07/2011-06/2015	433MHz FW931A159AB	L538	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2026-12/2026	433MHz	L461	●	●	○	A	433MHz	Continental	●	●

Land Rover	Range Rover Sport	10/2022-12/2025	433MHz	L461	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2021-09/2022	433MHz M8E21A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2017-09/2022	433MHz GX631A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2017-09/2022	433MHz FW931A159AB	L494	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2016-12/2016	433MHz FW931A159AB	L494	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2016-12/2016	433MHz GX631A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	07/2013-12/2015	433MHz AH521A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	07/2013-12/2015	433MHz FW931A159AB	L494	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	07/2013-12/2015	315MHz AH521A159CA	L494	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Sport	07/2013-12/2015	433MHz GX631A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2010-06/2013	433MHz BH521A159AA	L320	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2010-06/2013	433MHz AH521A159AA	L320	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2010-06/2013	315MHz BH521A159CA	L320	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2010-06/2013	433MHz GX631A159AA	L320	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2010-06/2013	315MHz AH521A159CA	L320	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2010-06/2013	433MHz FW931A159AB	L320	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2005-12/2009	315MHz	L320	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Sport	01/2005-12/2009	433MHz	L320	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Velar	01/2021-12/2026	433MHz M8E21A159AA	L560	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Velar	01/2019-12/2023	433MHz GX631A159AA	L560	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Velar	01/2017-12/2018	433MHz	L560	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2026-12/2026	433MHz M8E21A159AA	L460	●	●	○	A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2022-12/2025	433MHz M8E21A159AA	L460	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2022-12/2023	433MHz GX631A159AA	L460	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	02/2020-12/2021	433MHz M8E21A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2017-12/2021	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2016-12/2016	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2016-12/2016	433MHz FW931A159AB	L405	●	●	○	0/A	433MHz	Continental	●	●

Land Rover	Range Rover Vogue	01/2013-12/2015	433MHz FW931A159AB	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2013-12/2015	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2013-12/2015	433MHz AH521A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2013-12/2015	315MHz AH521A159CA	L405	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2010-12/2012	433MHz AH521A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2010-12/2012	315MHz BH521A159CA	L322	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2010-12/2012	433MHz BH521A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2010-12/2012	315MHz AH521A159CA	L322	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2010-12/2012	433MHz GX631A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2005-12/2009	315MHz	L322	●	●	○	0/A	315MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2005-12/2009	433MHz	L322	●	●	○	0/A	433MHz	Continental	●	●
Land Rover	Range Rover Vogue	01/2002-12/2004	433MHz	L322	●	●	○	0/A	433MHz	Huf/Beru	●	●
Lexus	ES Series	08/2018-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	GS Series	01/2012-12/2023	315MHz PMV- C010		●	●	○	0	315MHz	Pacific	●	●
Lexus	GS Series	08/2005-12/2011	315MHz PMV- 107J/1017/C11 A/1037		●	●	○	0	315MHz	Pacific	●	●
Lexus	GX Series	01/2024-12/2026	315MHz PMV- G001/E005/H00 0		●	●	○	0/A	315MHz	Pacific	●	●
Lexus	IS Series	10/2024-12/2026	315MHz PMV- G001/E005/H00 0		●	●	○	0	315MHz	Pacific	●	●
Lexus	IS Series	09/2020-12/2024	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	IS Series	04/2013-12/2020	315MHz PMV- C010		●	●	○	0	315MHz	Pacific	●	●
Lexus	LBX	12/2023-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	LC Series	10/2024-12/2026	315MHz PMV- G001/E005/H00 0		●	●	○	0	315MHz	Pacific	●	●
Lexus	LC Series	11/2021-12/2026	433MHz PMV- E100		●	●	○	0/A	433MHz	Pacific	●	●
Lexus	LC Series	01/2017-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	LM Series	11/2023-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	LS Series	11/2024-12/2026	315MHz PMV- G001/E005/H00 0		●	●	○	0	315MHz	Pacific	●	●
Lexus	LS Series	10/2017-12/2025	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●

Lexus	LS Series	09/2012-12/2021	315MHz PMV-C010		●	●	○	0	315MHz	Pacific	●	●
Lexus	LS Series	01/2006-08/2012	315MHz PMV-107J/1017/C11A/1037		●	●	○	0	315MHz	Pacific	●	●
Lexus	LX Series	01/2015-12/2024	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	NX Series	06/2024-12/2026	315MHz PMV-G001/E005/H000		●	●	○	0	315MHz	Pacific	●	●
Lexus	NX Series	11/2021-12/2026	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	NX Series	01/2014-12/2024	315MHz PMV-C010		●	●	○	0	315MHz	Pacific	●	●
Lexus	RC Series	01/2025-12/2026	315MHz PMV-G001/E005/H000		●	●	○	0	315MHz	Pacific	●	●
Lexus	RC Series	01/2020-12/2025	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	RC Series	01/2014-01/2023	315MHz PMV-C010		●	●	○	0	315MHz	Pacific	●	●
Lexus	RX Series	10/2024-12/2026	315MHz PMV-G001/E005/H000		●	●	○	0	315MHz	Pacific	●	●
Lexus	RX Series	09/2015-12/2025	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	RX Series	07/2013-09/2015	315MHz PMV-C010		●	●	○	0	315MHz	Pacific	●	●
Lexus	RX Series	01/2006-01/2021	315MHz PMV-107J/1017/C11A/1037		●	●	○	0	315MHz	Pacific	●	●
Lexus	RZ Series	10/2024-12/2026	315MHz PMV-G001/E005/H000		●	●	○	0	315MHz	Pacific	●	●
Lexus	RZ Series	01/2023-12/2026	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lexus	SC Series	08/2006-12/2010	315MHz PMV-107J/1017/C11A/1037		●	●	○	0	315MHz	Pacific	●	●
Lexus	UX Series	01/2024-12/2026	315MHz PMV-G001/E005/H000		●	●	○	0	315MHz	Pacific	●	●
Lexus	UX Series	10/2018-12/2026	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
Lincoln	Aviator	05/2019-12/2024	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
Lincoln	Corsair	05/2019-12/2026	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
Lincoln	Town Car	07/2005-12/2011	315MHz		●	●	○	S	315MHz	Lear	●	●
Lotus	Eletre	06/2023-12/2026	433MHz		●	●	○	C	433MHz	Schrader	●	●
Lotus	Elise	01/2008-12/2022	433MHz		○	●	○	A	433MHz	Schrader	●	●
Lotus	Emeya	06/2024-12/2026	433MHz		○	●	○	C	433MHz	Schrader	●	●
Lotus	Emira	01/2023-12/2026	433MHz		○	●	○	A	433MHz	Schrader	●	●
Lotus	Emira	01/2023-12/2026	433MHz 8891175852		○	●	○	C	433MHz	Schrader	●	●
Lotus	Evora	01/2010-12/2022	433MHz		○	●	○	A	433MHz	Schrader	●	●
Maserati	Ghibli	01/2021-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Maserati	Ghibli	01/2018-12/2020	433MHz	M156/M157	●	●	○	0/A	433MHz	Schrader	●	●

Maserati	Ghibli	01/2018-12/2018	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Maserati	Ghibli	01/2014-12/2017	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Maserati	Ghibli	01/2013-12/2017	433MHz	M156/M157	●	●	○	0/A	433MHz	Schrader	●	●
Maserati	GranCabrio	01/2023-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Maserati	GranTurismo	01/2023-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Maserati	GranTurismo	01/2011-12/2017	315MHz	M145 GL	●	●	○	0/A	315MHz	Huf/Beru	●	●
Maserati	GranTurismo	01/2008-12/2010	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Maserati	GranTurismo Sport	01/2019-12/2023	315MHz		●	●	○	0/A	315MHz	Huf	●	●
Maserati	GranTurismo Sport	08/2017-12/2018	315MHz		●	●	○	0/A	315MHz	Huf	●	●
Maserati	GranTurismo Sport	01/2013-07/2017	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Maserati	Grecale	01/2023-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Maserati	Grecale	01/2022-12/2023	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Maserati	Levante	01/2019-12/2026	315MHz 50554748		●	●	○	0/A	315MHz	Continental	●	●
Maserati	Levante	01/2018-12/2020	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Maserati	Levante	01/2018-12/2019	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Maserati	Levante	01/2017-12/2017	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Maserati	Levante	01/2015-12/2017	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Maserati	MC20	01/2022-12/2026	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Maserati	MC20	01/2020-12/2025	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Maserati	Quattroporte	01/2018-12/2026	433MHz 670002790		●	●	○	0/A	433MHz	Schrader	●	●
Maserati	Quattroporte	01/2018-12/2018	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Maserati	Quattroporte	01/2014-12/2017	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Maserati	Quattroporte	01/2013-12/2017	433MHz 670002790		●	●	○	0/A	433MHz	Schrader	●	●
Maserati	Quattroporte	01/2004-12/2010	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Maserati	Spyder	07/2001-12/2008	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Maybach	Landaulet	01/2018-12/2020	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
Maybach	Landaulet	10/2008-12/2014	433MHz	Ma009-127	●	●	○	0/S	433MHz	Huf/Beru	●	●
Maybach	Maybach 57	02/2002-12/2013	433MHz	Ma007	●	●	○	0/S	433MHz	Huf/Beru	●	●
Maybach	Maybach 62	02/2002-12/2013	433MHz	Ma007	●	●	○	0/S	433MHz	Huf/Beru	●	●
Maybach	S Series	01/2021-12/2024	433MHz	223	●	●	○	0/A	433MHz	Schrader	●	●
Maybach	S Series	01/2021-12/2024	315MHz	223	●	●	○	0/A	315MHz	Schrader	●	●
Maybach	S Series	01/2021-12/2024	433MHz A0009058413	223	●	●	○	A/0	433MHz	Schrader	●	●
Maybach	S Series	01/2021-12/2024	315MHz A0009058513	223	●	●	○	A/0	315MHz	Schrader	●	●
Maybach	S Series	01/2015-12/2021	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
Mazda	CX-5	01/2012-12/2017	Indirect		○	○	○	A	N/A	N/A	Indirect	●
McLaren	540C	01/2016-12/2018	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
McLaren	540C	01/2015-12/2022	433MHz RDE011		●	●	○	0/A	433MHz	Huf/Beru	●	●
McLaren	570S	01/2016-12/2018	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
McLaren	570S	01/2015-12/2022	433MHz RDE011		●	●	○	0/A	433MHz	Huf/Beru	●	●
McLaren	600LT	01/2018-12/2022	433MHz RDE011		●	●	○	0/A	433MHz	Huf/Beru	●	●
McLaren	600LT	01/2018-12/2018	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
McLaren	620R	12/2019-12/2021	433MHz RDE011		●	●	○	0/A	433MHz	Huf/Beru	●	●
McLaren	625C	01/2015-12/2018	315MHz 36118378681		●	●	○	A	315MHz	Huf/Beru	●	●

McLaren	650S	01/2014-12/2018	315MHz 36118378681		●	●	○	A	315MHz	Huf/Beru	●	●
McLaren	675LT	01/2015-12/2018	315MHz 36118378681		●	●	○	A	315MHz	Huf/Beru	●	●
McLaren	720S	01/2023-12/2023	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	720S	01/2017-12/2022	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
McLaren	750S	01/2023-12/2025	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	765LT	01/2023-12/2023	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	765LT	07/2021-12/2022	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
McLaren	MP4-12C	01/2012-12/2014	315MHz 36118378681		●	●	○	A	315MHz	Huf/Beru	●	●
McLaren	MP4-12C	01/2011-12/2014	315MHz F1001495002		●	●	○	A	315MHz	Huf/Beru	●	●
McLaren	P1	01/2016-12/2017	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
McLaren	P1	01/2013-12/2015	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
McLaren	Senna	01/2018-12/2019	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Senna	01/2017-12/2017	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Mercedes	A Class	06/2025-12/2026	433MHz A0009058821	177	●	●	○	0	433MHz	BHSENS	●	●
Mercedes	A Class	06/2025-12/2026	315MHz A0009058921	177	●	●	○	0	315MHz	BHSENS	●	●
Mercedes	A Class	06/2018-12/2026	433MHz	177	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	A Class	06/2018-12/2026	315MHz A0009054204	177	●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	A Class	01/2015-12/2019	315MHz A0009050130	176	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	A Class	04/2014-05/2018	433MHz	176	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	A Class	01/2012-03/2014	433MHz	176	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	AMG	01/2010-12/2020	433MHz	W197	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	AMG GT	06/2023-12/2026	315MHz A0009058513	192	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	AMG GT	06/2023-12/2026	433MHz A0009058413	192	●	●	○	A/0	433MHz	Schrader	●	●
Mercedes	AMG GT	01/2022-12/2026	433MHz	192	●	●	○	A/0	433MHz	Schrader	●	●
Mercedes	AMG GT	11/2018-12/2026	433MHz	290	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	AMG GT	11/2018-12/2026	315MHz	290	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	AMG GT	01/2014-12/2023	433MHz	C190	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	B Class	11/2025-12/2026	433MHz A0009058821		●	●	○	0	433MHz	BHSENS	●	●
Mercedes	B Class	11/2025-12/2026	315MHz A0009058921		●	●	○	0	315MHz	BHSENS	●	●
Mercedes	B Class	02/2019-12/2026	433MHz A0009054104	247	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	B Class	02/2019-12/2026	315MHz	247	●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	B Class	11/2011-01/2019	433MHz	246	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	C Class	09/2022-12/2026	433MHz A0009058413	206	●	●	○	A/0	433MHz	Schrader	●	●
Mercedes	C Class	09/2022-12/2026	315MHz A0009058513	206	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	C Class	06/2021-12/2026	433MHz	206	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	C Class	01/2020-12/2022	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	C Class	06/2018-12/2023	433MHz A0009053907	C205	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	C Class	01/2016-12/2021	315MHz A0009052202		●	●	○	0/A	315MHz	Schrader	●	●

Mercedes	C Class	01/2015-12/2019	315MHz A0009050130		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	C Class	04/2007-12/2020	433MHz	W205	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Citan	09/2021-06/2026	433MHz A4204012400		●	●	○	0	433MHz	Continental	●	●
Mercedes	Citan	01/2017-12/2019	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mercedes	Citan	01/2012-12/2023	433MHz	415	●	●	○	0	433MHz	Schrader	●	●
Mercedes	CL Class	01/2010-12/2015	433MHz	216	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	CL Class	07/2006-06/2019	433MHz A0009054100	216	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	CL Class	01/1998-12/2006	433MHz	215	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	CLA Class	11/2025-12/2026	433MHz A0009058821	178	●	●	○	0	433MHz	BHSENS	●	●
Mercedes	CLA Class	11/2025-12/2026	315MHz A0009058921	178	●	●	○	0	315MHz	BHSENS	●	●
Mercedes	CLA Class	05/2019-06/2026	433MHz	118	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	CLA Class	05/2019-06/2026	315MHz A0009054204	118	●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	CLA Class	01/2019-12/2020	315MHz A0009050130	117	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	CLA Class	01/2015-12/2017	315MHz	117	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	CLA Class	06/2014-04/2019	433MHz	117	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	CLA Class	12/2012-05/2014	433MHz	117	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	CLA Class EV	11/2025-12/2026	433MHz A0009058821	174	●	●	○	0	433MHz	BHSENS	●	●
Mercedes	CLA Class EV	11/2025-12/2026	315MHz A0009058921	174	●	●	○	0	315MHz	BHSENS	●	●
Mercedes	CLC Class	01/2008-06/2018	433MHz	216	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	CLE Class	06/2023-12/2026	315MHz A0009058513	236	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	CLE Class	06/2023-12/2026	433MHz A0009058413	236	●	●	○	A/0	433MHz	Schrader	●	●
Mercedes	CLK Class	01/2002-06/2018	433MHz	209	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	CLS Class	01/2018-06/2026	433MHz	257	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	CLS Class	01/2018-06/2026	315MHz	257	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	CLS Class	07/2009-12/2017	433MHz	218	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	CLS Class	10/2004-12/2004	433MHz A0055422318	219	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	CLS Class	09/2004-12/2011	433MHz A0025408017	219	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	E Class	01/2025-12/2026	433MHz A0009058821	214	●	●	○	0	433MHz	BHSENS	●	●
Mercedes	E Class	01/2025-12/2026	315MHz A0009058921	214	●	●	○	0	315MHz	BHSENS	●	●
Mercedes	E Class	10/2023-12/2026	315MHz A0009058513	214	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	E Class	10/2023-12/2026	433MHz A0009058413	214	●	●	○	A/0	433MHz	Schrader	●	●
Mercedes	E Class	01/2016-12/2023	315MHz	213	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	E Class	11/2015-12/2023	433MHz	W213/BR238	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	E Class	06/2014-12/2018	433MHz	W212	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	E Class	01/2014-10/2015	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mercedes	E Class	07/2009-05/2014	433MHz	W212/C207	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	E Class	06/2005-10/2011	433MHz	W211	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	E Class	01/2002-05/2005	433MHz	W211	●	●	○	0/A	433MHz	Huf/Beru	●	●

Mercedes	E Class AMG	01/1999-12/2002	433MHz	W210	●	●	○	0/S	433MHz	Huf/Beru	●	●
Mercedes	EQA	11/2025-12/2026	433MHz A0009058821		●	●	○	0	433MHz	BHSENS	●	●
Mercedes	EQA	11/2025-12/2026	315MHz A0009058921		●	●	○	0	315MHz	BHSENS	●	●
Mercedes	EQA	01/2020-12/2026	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	EQA	01/2020-12/2026	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	EQB	11/2025-12/2026	433MHz A0009058821		●	●	○	0	433MHz	BHSENS	●	●
Mercedes	EQB	11/2025-12/2026	315MHz A0009058921		●	●	○	0	315MHz	BHSENS	●	●
Mercedes	EQB	01/2022-12/2026	315MHz		●	●	○	0	315MHz	Huf/Beru	●	●
Mercedes	EQB	01/2021-12/2026	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	EQC	01/2019-06/2026	433MHz	293	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	EQC	01/2019-06/2026	315MHz	293	●	●	○	0	315MHz	Schrader	●	●
Mercedes	EQE	09/2022-12/2026	433MHz A0009058413	295	●	●	○	A/0	433MHz	Schrader	●	●
Mercedes	EQE	09/2022-12/2026	315MHz A0009058513	295	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	EQE	01/2022-12/2026	433MHz	295	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	EQE	01/2022-12/2026	315MHz	295	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	EQS	09/2022-12/2026	433MHz A0009058413	297	●	●	○	A/0	433MHz	Schrader	●	●
Mercedes	EQS	09/2022-12/2026	315MHz A0009058513	297	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	EQS	01/2021-12/2026	433MHz	297	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	EQS	01/2021-12/2026	315MHz	297	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	EQV	01/2024-12/2026	433MHz A0009057205		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	G Class	11/2025-12/2026	433MHz A0009058821		●	●	○	0	433MHz	BHSENS	●	●
Mercedes	G Class	11/2025-12/2026	315MHz A0009058921		●	●	○	0	315MHz	BHSENS	●	●
Mercedes	G Class	06/2024-12/2026	433MHz A0009054104	465	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	G Class	06/2024-12/2026	315MHz A0009054204	465	●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	G Class	06/2018-06/2026	433MHz	463	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	G Class	06/2018-06/2026	315MHz	463	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	G Class	01/2018-12/2018	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	G Class	04/2007-05/2018	433MHz	G463/461	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GL Class	01/2013-06/2019	433MHz	X166	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GL Class	06/2009-12/2012	433MHz	X164	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GL Class	04/2006-09/2009	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Mercedes	GLA Class	11/2025-12/2026	433MHz A0009058821		●	●	○	0	433MHz	BHSENS	●	●
Mercedes	GLA Class	11/2025-12/2026	315MHz A0009058921		●	●	○	0	315MHz	BHSENS	●	●
Mercedes	GLA Class	01/2020-12/2026	433MHz A0009054104		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLA Class	01/2020-12/2026	315MHz A0009054204		●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	GLA Class	01/2015-12/2020	315MHz A0009050130		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	GLA Class	12/2013-06/2020	433MHz	X156	●	●	○	0/A	433MHz	Schrader	●	●

Mercedes	GLB Class	11/2025-12/2026	433MHz A0009058821		●	●	○	0	433MHz	BHSENS	●	●
Mercedes	GLB Class	11/2025-12/2026	315MHz A0009058921		●	●	○	0	315MHz	BHSENS	●	●
Mercedes	GLB Class	01/2019-12/2026	433MHz	247	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLB Class	01/2019-12/2026	315MHz	247	●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	GLC Class	09/2022-12/2026	315MHz A0009058513	254	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	GLC Class	01/2022-12/2026	315MHz	254	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	GLC Class	09/2016-12/2022	433MHz A0009053907	C253	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLC Class	01/2015-12/2021	315MHz	X253	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	GLC Class	01/2015-07/2019	433MHz	X253	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLE Class	10/2025-12/2026	433MHz A0009058821		●	●	○	0	433MHz	BHSENS	●	●
Mercedes	GLE Class	10/2025-12/2026	315MHz A0009058921		●	●	○	0	315MHz	BHSENS	●	●
Mercedes	GLE Class	01/2020-12/2021	315MHz A0009052202		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	GLE Class	10/2018-12/2026	433MHz	V167	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLE Class	01/2018-12/2026	315MHz	W167	●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	GLE Class	04/2015-11/2019	433MHz	X166/C292	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLE Class	01/2015-12/2020	315MHz A0009050130		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	GLK Class	10/2015-06/2019	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLK Class	01/2008-09/2015	433MHz	X204	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLS Class	06/2025-12/2026	433MHz A0009058821		●	●	○	0	433MHz	BHSENS	●	●
Mercedes	GLS Class	06/2025-12/2026	315MHz A0009058921		●	●	○	0	315MHz	BHSENS	●	●
Mercedes	GLS Class	01/2020-12/2026	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	GLS Class	07/2019-12/2026	433MHz	X167	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLS Class	01/2016-12/2019	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	GLS Class	01/2013-06/2019	433MHz	X166	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GT	01/2015-12/2021	315MHz A0009050130		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	GT-S AMG	01/2014-12/2019	433MHz	C190	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	M Class	01/2010-12/2014	433MHz	W166	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	M Class	01/2005-05/2011	433MHz	W164	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	Marco Polo	01/2014-12/2022	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Metris	01/2015-12/2023	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	ML Class	06/2011-12/2019	433MHz	W166	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	ML Class	08/2009-05/2011	433MHz	W164	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	ML Class	12/2004-07/2009	433MHz	W164	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	R Class	08/2009-06/2018	433MHz	W251	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	R Class	06/2005-12/2014	433MHz Continental	W251	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	S Class	09/2020-12/2026	433MHz	223	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	S Class	09/2020-12/2026	433MHz A0009058413	223	●	●	○	A/0	433MHz	Schrader	●	●
Mercedes	S Class	09/2020-12/2026	315MHz A0009058513	223	●	●	○	A/0	315MHz	Schrader	●	●
Mercedes	S Class	09/2020-12/2026	315MHz	223	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	S Class	01/2015-12/2021	315MHz		●	●	○	0/A	315MHz	Schrader	●	●

Mercedes	S Class	06/2009-12/2020	433MHz	W222/C217	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	S Class	10/2005-05/2009	433MHz	W221	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	S Class	07/1999-09/2005	433MHz	W220	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	S Class coupe	01/2003-09/2005	433MHz	C215	●	●	○	0/S	433MHz	Huf/Beru	●	●
Mercedes	S Class coupe	07/1999-12/2002	433MHz	C215	●	●	○	0/S	433MHz	Huf/Beru	●	●
Mercedes	SL Class	09/2021-12/2026	433MHz	232	●	●	○	A/O	433MHz	Schrader	●	●
Mercedes	SL Class	09/2021-12/2026	315MHz	232	●	●	○	A/O	315MHz	Schrader	●	●
Mercedes	SL Class	09/2021-12/2026	433MHz A0009058413	232	●	●	○	A/O	433MHz	Schrader	●	●
Mercedes	SL Class	09/2021-12/2026	315MHz A0009058513	232	●	●	○	A/O	315MHz	Schrader	●	●
Mercedes	SL Class	01/2012-12/2021	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	SL Class	01/2012-12/2020	433MHz	W231	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	SL Class	01/2005-06/2012	433MHz	W230	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	SL Class	01/2000-04/2005	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	SL Roadster	08/2001-06/2005	433MHz	R230	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	SLC Class	01/2016-12/2021	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	SLC Class	01/2016-06/2020	433MHz	R172	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	SLK Class	04/2007-05/2019	315MHz	R172	●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	SLK Class	01/2004-12/2021	433MHz	R171, R172	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	SLR Class	04/2004-12/2015	433MHz	R199	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	SLR McLaren	01/2004-12/2011	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	SLS Class	01/2010-06/2019	433MHz	197	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	SLS Class	01/2010-12/2015	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Mercedes	Sprinter	06/2024-12/2026	433MHz A0009052816		●	●	○	0/A	433MHz	BHSENS	●	●
Mercedes	Sprinter	06/2024-12/2026	433MHz 6-wheel		○	●	○	A	433MHz	BHSENS	●	●
Mercedes	Sprinter	01/2018-12/2026	433MHz A0009054104		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	Sprinter	11/2011-06/2020	433MHz	906 (NVC3)	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Sprinter	06/2006-10/2011	433MHz	W906	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	Sprinter Combi	10/2018-06/2021	433MHz	906	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	Sprinter Combi	11/2011-09/2018	433MHz	906	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Sprinter Combi	01/2006-10/2011	433MHz	906	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	V Class	01/2024-12/2026	433MHz A0009057205		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	V Class	01/2014-12/2026	433MHz	W447	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Vario	01/2014-12/2019	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Vario	01/2012-12/2013	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
Mercedes	Viano	06/2014-12/2021	433MHz A4479050500	W639	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Viano	07/2003-05/2014	433MHz A0025409517	W639	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	Vito	01/2024-12/2026	433MHz A0009057205		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	Vito	07/2014-12/2026	433MHz	W447	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Vito	05/2003-06/2014	433MHz	W639	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	X Class	01/2017-12/2020	433MHz		●	●	○	0	433MHz	Pacific	●	●
Mini	Aceman	05/2024-12/2026	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Mini	Aceman	11/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●

Mini	Cabrio	11/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Mini	Cabrio	11/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Mini	Cabrio	11/2015-06/2024	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
Mini	Cabrio	07/2014-12/2015	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Clubman	07/2015-06/2024	433MHz		●	●	○	A	433MHz	Continental	●	●
Mini	Clubman	07/2014-12/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Clubman	08/2007-12/2016	433MHz 36236781847		●	●	○	A	433MHz	Huf/Beru	●	●
Mini	Clubvan	01/2016-12/2019	433MHz		●	●	○	A	433MHz	Continental	●	●
Mini	Clubvan	07/2012-12/2015	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Cooper	11/2023-12/2026	433MHz	J01	○	●	○	A	433MHz	Huf/Beru	●	●
Mini	Cooper	11/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Mini	Countryman	11/2023-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Mini	Countryman	11/2023-12/2026	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Mini	Countryman	07/2015-06/2024	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
Mini	Countryman	07/2014-12/2018	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Countryman	01/2009-06/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Coupe	07/2014-12/2015	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Coupe	07/2011-06/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Mini	03/2024-12/2026	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Mini	Mini	03/2024-12/2026	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
Mini	Mini	01/2017-12/2022	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Mini	Mini	01/2014-12/2016	433MHz		●	●	○	0*/A	433MHz	Huf/Beru	●	●
Mini	Mini	12/2013-06/2024	433MHz Continental	F55/F56	●	●	○	A	433MHz	Continental	●	●
Mini	Mini	01/2009-12/2015	433MHz OYGTSSRE4D		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Mini	03/2006-11/2013	433MHz Continental	R56	●	●	○	0*/A	433MHz	Continental	●	●
Mini	Paceman	07/2018-12/2019	433MHz		●	●	○	A	433MHz	Continental	●	●
Mini	Paceman	07/2014-06/2018	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Paceman	01/2009-06/2014	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Roadster	05/2014-12/2015	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mini	Roadster	01/2011-12/2014	433MHz 36106856227		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mitsubishi	Eclipse Cross	11/2021-12/2026	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Galant	07/2006-12/2013	315MHz		●	●	○	0	315MHz	Schrader	●	●
Mitsubishi	Galant	01/2003-12/2006	433MHz		●	●	○	0	433MHz	Schrader	●	●
Mitsubishi	i-MiEV	01/2010-12/2019	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Mirage	04/2021-12/2023	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Mirage	07/2013-03/2021	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Pajero	01/2016-12/2022	433MHz	V80	●	●	○	0	433MHz	Continental	●	●
Mitsubishi	Proudia	01/2012-12/2017	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	RVR	01/2012-12/2016	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	Ariya	11/2023-12/2026	315MHz		●	●	○	0*	315MHz	Continental	●	●
Nissan	Ariya	01/2022-10/2023	315MHz		●	●	○	0*	315MHz	Continental	●	●
Nissan	Caravan	12/2021-12/2022	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Cima	06/2017-12/2022	315MHz 407005UVOA		●	●	○	0	315MHz	Pacific	●	●
Nissan	Cima	05/2012-12/2019	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Cube	01/2013-12/2016	315MHz		●	●	○	0	315MHz	Pacific	●	●

Nissan	Cube	03/2012-12/2012	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Cube	11/2011-12/2015	315MHz 407001LA0E		●	●	○	0	315MHz	Pacific	●	●
Nissan	Cube	10/2010-12/2016	315MHz 407003AN1A		●	●	○	0	315MHz	Continental	●	●
Nissan	Cube	10/2009-02/2012	315MHz		●	●	○	0	315MHz	Schrader	●	●
Nissan	Cube	07/2009-10/2009	315MHz 40700JA00C		●	●	○	0	315MHz	Schrader	●	●
Nissan	Cube	02/2009-07/2009	315MHz 40700JA01C		●	●	○	0	315MHz	Schrader	●	●
Nissan	Elgrand	08/2010-12/2026	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Fairlady Z	08/2022-12/2026	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	FUGA	11/2017-12/2022	315MHz 407005UVOA		●	●	○	0	315MHz	Pacific	●	●
Nissan	FUGA	01/2015-12/2022	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	FUGA	06/2012-12/2022	315MHz 40700JK00A		●	●	○	0	315MHz	Pacific	●	●
Nissan	FUGA	06/2012-10/2017	315MHz 407001LA0E		●	●	○	0	315MHz	Pacific	●	●
Nissan	FUGA	01/2008-05/2012	315MHz		●	●	○	0	315MHz	Schrader	●	●
Nissan	GT-R	09/2022-12/2025	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	GT-R	09/2022-12/2025	433MHz 407006GP1A		●	●	○	0	433MHz	Pacific	●	●
Nissan	GT-R	05/2020-08/2022	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	GT-R	11/2017-12/2024	315MHz 407005UVOA		●	●	○	0	315MHz	Pacific	●	●
Nissan	GT-R	11/2013-08/2022	433MHz 4070062B0A		●	●	○	0	433MHz	Pacific	●	●
Nissan	GT-R	11/2013-11/2017	315MHz 40700JK01B		●	●	○	0	315MHz	Pacific	●	●
Nissan	GT-R	06/2011-04/2020	433MHz		●	●	○	0	433MHz	Schrader	●	●
Nissan	GT-R	11/2010-04/2020	315MHz		●	●	○	0	315MHz	Schrader	●	●
Nissan	GT-R	12/2008-05/2011	433MHz		●	●	○	0	433MHz	Schrader	●	●
Nissan	GT-R	03/2008-12/2010	315MHz 40700JA00C		●	●	○	0	315MHz	Schrader	●	●
Nissan	GT-R	03/2008-12/2009	315MHz 40700JA01C		●	●	○	0	315MHz	Schrader	●	●
Nissan	GT-R	11/2007-11/2010	315MHz		●	●	○	0	315MHz	Schrader	●	●
Nissan	Juke	10/2019-12/2021	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Juke	05/2014-09/2019	433MHz		●	●	○	0	433MHz	Pacific	●	●
Nissan	Juke	01/2013-10/2014	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Juke	03/2012-12/2012	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Juke	07/2011-02/2012	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	Juke	07/2010-12/2020	315MHz 407001LA0E		●	●	○	0	315MHz	Pacific	●	●
Nissan	Juke	07/2010-03/2012	315MHz 407001AA0B		●	●	○	0	315MHz	Schrader	●	●
Nissan	Kicks	09/2024-12/2026	433MHz		●	●	○	C	433MHz	Pacific	●	●
Nissan	Kicks	06/2024-12/2026	315MHz		●	●	○	C	315MHz	Pacific	●	●
Nissan	Kicks	03/2023-12/2024	433MHz 407006LY0A		●	●	○	0	433MHz	Pacific	●	●
Nissan	Kicks	09/2019-12/2026	433MHz 407006LB0A		●	●	○	0	433MHz	Pacific	●	●
Nissan	Kicks	11/2016-03/2021	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Leaf	02/2020-12/2025	433MHz		●	●	○	0	433MHz	Continental	●	●

Nissan	Leaf	01/2018-01/2020	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Leaf	11/2014-12/2017	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Leaf	05/2014-02/2016	433MHz 407006WYOB		●	●	○	0	433MHz	Pacific	●	●
Nissan	Leaf	01/2013-12/2018	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	Leaf	10/2010-12/2012	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	March	04/2016-12/2023	433MHz		●	●	○	0	433MHz	Pacific	●	●
Nissan	March	04/2016-12/2020	433MHz 407003VUOA		●	●	○	0	433MHz	Continental	●	●
Nissan	Murano	01/2013-09/2014	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Murano	11/2011-12/2012	315MHz 40700JKO0E		●	●	○	0	315MHz	Pacific	●	●
Nissan	Murano	10/2008-08/2012	315MHz		●	●	○	0	315MHz	Schrader	●	●
Nissan	Murano	08/2006-09/2008	315MHz		●	●	○	0	315MHz	Schrader	●	●
Nissan	Murano	09/2002-07/2006	315MHz		●	●	○	0	315MHz	Schrader	●	●
Nissan	Note	08/2013-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	NV200	02/2014-12/2026	433MHz		●	●	○	0	433MHz	Pacific	●	●
Nissan	Primera	01/2002-12/2009	433MHz		●	●	○	0	433MHz	Schrader	●	●
Nissan	Skyline	11/2013-12/2026	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	Sylphy	07/2020-12/2022	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Sylphy	05/2019-12/2022	433MHz 407006LB0A		●	●	○	0	433MHz	Pacific	●	●
Nissan	Sylphy	10/2017-12/2021	433MHz 407004CB0B		●	●	○	0	433MHz	Continental	●	●
Nissan	Sylphy	12/2015-09/2017	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Nissan	Teana	01/2018-12/2020	433MHz 407004CB0B		●	●	○	0	433MHz	Continental	●	●
Nissan	Teana	04/2016-12/2022	433MHz 407006WYOB		●	●	○	0	433MHz	Pacific	●	●
Nissan	Teana	01/2014-12/2019	433MHz 407003VUOA		●	●	○	0	433MHz	Continental	●	●
Nissan	Teana	02/2013-04/2018	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	X-Trail	10/2023-06/2026	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	X-Trail	09/2022-09/2023	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	X-Trail	06/2021-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	X-Trail	05/2017-04/2022	433MHz 407004CB0B		●	●	○	0	433MHz	Continental	●	●
Nissan	X-Trail	02/2014-04/2017	433MHz		●	●	○	0	433MHz	Continental	●	●
Opel/Vauxhall	Astra H	01/2004-10/2009	433MHz 13172567		●	●	○	A	433MHz	Schrader	●	●
Opel/Vauxhall	Corsa	01/2020-12/2024	Indirect	F/Mk5	○	○	○	A	N/A	N/A	Indirect	●
Opel/Vauxhall	Grandland	01/2017-12/2024	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Opel/Vauxhall	Signum	01/2002-12/2011	433MHz		○	●	○	A	433MHz	Schrader	●	●
Opel/Vauxhall	Vectra	01/2002-10/2012	433MHz	Oe86/GM Z3200	○	●	○	A	433MHz	Schrader	●	●
Peugeot	1007	01/2004-12/2011	433MHz		●	●	○	0	433MHz	Continental	●	●
Peugeot	2008	02/2013-12/2024	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	207	10/2013-12/2016	433MHz	A7	●	●	○	0	433MHz	Schrader	●	●
Peugeot	207	11/2005-09/2013	433MHz	A7	●	●	○	0	433MHz	Continental	●	●
Peugeot	208	01/2012-12/2024	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	3008	06/2016-12/2024	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	3008	09/2013-12/2019	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Peugeot	3008	11/2008-08/2013	433MHz	T84	●	●	○	0	433MHz	Schrader	●	●
Peugeot	307	03/2007-12/2008	433MHz		●	●	○	0	433MHz	Schrader	●	●

Peugeot	307	01/2001-02/2007	433MHz		●	●	○	0	433MHz	Continental	●	●
Peugeot	308	01/2020-12/2024	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Peugeot	308	06/2013-12/2019	433MHz		●	●	○	0	433MHz	Schrader	●	●
Peugeot	308	05/2007-05/2013	433MHz		●	●	○	0	433MHz	Schrader	●	●
Peugeot	407	01/2003-12/2012	433MHz		●	●	○	0	433MHz	Continental	●	●
Peugeot	5008	01/2017-12/2025	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Peugeot	5008	09/2013-12/2022	433MHz		●	●	○	0	433MHz	Schrader	●	●
Peugeot	508	07/2017-12/2024	Indirect	R83	○	○	○	S	N/A	N/A	Indirect	●
Peugeot	508	10/2013-12/2022	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Peugeot	508	09/2010-09/2013	433MHz		●	●	○	0	433MHz	Continental	●	●
Peugeot	607	09/1999-09/2004	433MHz	6042/Z8	○	●	○	C	433MHz	Schrader	●	●
Peugeot	RCZ	10/2013-06/2017	433MHz	T75	●	●	○	0	433MHz	Schrader	●	●
Peugeot	RCZ	12/2009-09/2013	433MHz	T75	●	●	○	0	433MHz	Schrader	●	●
Peugeot	Rifter	07/2018-12/2024	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Polestar	Polestar 2	07/2020-12/2024	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Porsche	718 Boxster	01/2017-12/2026	433MHz	982	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	718 Boxster	01/2017-12/2026	315MHz	982	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	718 Cayman	01/2017-12/2026	433MHz	982C	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	718 Cayman	01/2017-12/2026	315MHz	982C	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	911	06/2025-12/2026	315MHz	992T	●	●	○	A	315MHz	Huf/Beru	●	●
Porsche	911	01/2019-05/2025	315MHz	992T	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	911	01/2019-12/2024	315MHz	992	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	911	02/2012-12/2016	433MHz	991	●	●	○	A	433MHz	Huf/Beru	●	●
Porsche	911	12/2011-12/2016	315MHz	991	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Boxster	01/2017-12/2026	315MHz	982SP	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Boxster	01/2004-12/2008	433MHz	987	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Cayenne	01/2015-12/2023	315MHz	9YA	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Cayenne	01/2010-12/2014	315MHz	92A	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Cayman	10/2019-12/2026	315MHz	CT4-2	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Cayman	01/2009-12/2016	433MHz	987C/981C/GT4-1	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Cayman	01/2009-12/2016	315MHz	987C/981C/GT4-1	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Macan	06/2025-12/2026	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Porsche	Macan	01/2024-05/2025	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Macan	01/2014-12/2023	433MHz	P0416/95B	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Macan	01/2014-12/2023	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Panamera	01/2024-12/2025	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Panamera	09/2017-12/2023	433MHz	970/971	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Panamera	01/2017-12/2023	315MHz	971	●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Panamera	01/2009-12/2020	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Porsche	Taycan	01/2020-12/2023	315MHz		●	●	○	0	315MHz	Huf/Beru	●	●
Renault	Alpine A110	01/2018-12/2023	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Alpine A110	01/2018-12/2022	433MHz 407003VUOA		●	●	○	0	433MHz	Continental	●	●
Renault	Captur	03/2022-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Captur	01/2016-12/2026	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Renault	Captur	01/2013-12/2019	433MHz 407005642R		●	●	○	0	433MHz	Schrader	●	●
Renault	Clio IV	01/2016-12/2019	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Renault	Kadjar	01/2016-05/2021	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Renault	Koleos	01/2014-07/2016	433MHz		●	●	○	0	433MHz	Continental	●	●

Renault	Koleos	01/2013-07/2016	433MHz 407003VU0A		●	●	○	0	433MHz	Continental	●	●
Renault	Koleos	06/2010-07/2016	315MHz		●	●	○	0	315MHz	Schrader	●	●
Renault	Koleos	01/2010-07/2016	433MHz 407001AY0A	H45	●	●	○	0	433MHz	Schrader	●	●
Renault	Koleos	01/2010-12/2013	315MHz 407001AA0B		●	●	○	0	315MHz	Schrader	●	●
Renault	Megane II	01/2005-12/2009	433MHz	B32/X84	●	●	●	0	433MHz	Continental	●	●
Renault	Megane III	01/2010-06/2017	433MHz	X95	●	●	○	0	433MHz	Continental	●	●
Renault	Megane IV	02/2021-12/2024	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Megane IV	02/2021-12/2023	433MHz 407004CB0A		●	●	○	0/A	433MHz	Continental	●	●
Renault	Megane IV	06/2017-01/2021	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Scenic I	01/1997-12/2003	433MHz	J64	●	●	●	0	433MHz	Schrader	●	●
Renault	Scenic II	01/2003-12/2009	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Scenic III	01/2009-06/2016	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Twingo	01/2022-12/2024	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Twingo	01/2018-12/2021	433MHz		●	●	○	0	433MHz	Schrader	●	●
Renault	Twingo	01/2016-12/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Rivian	R1S	01/2022-12/2026	433MHz		○	●	○	A	433MHz	BHSENS	●	●
Rolls Royce	Cullinan	08/2024-12/2026	315MHz		○	●	○	A	315MHz	Schrader	●	●
Rolls Royce	Ghost	12/2024-12/2026	315MHz 36106887146		○	●	○	A	315MHz	Schrader	●	●
Rolls Royce	Ghost	08/2020-12/2026	433MHz 36106887147		○	●	○	A	433MHz	Schrader	●	●
Rolls Royce	Ghost	01/2020-06/2024	433MHz 36106877937	RR21	○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Ghost	04/2014-12/2021	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Ghost	12/2009-03/2014	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Phantom	06/2025-12/2026	315MHz		○	●	○	A	315MHz	Schrader	●	●
Rolls Royce	Phantom	01/2017-12/2026	433MHz MRXAG5SP4	RR11/RR02/RR1 2	○	●	○	A	433MHz	Schrader	●	●
Rolls Royce	Phantom	01/2012-12/2017	433MHz	RR01	○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Phantom	01/2007-12/2022	433MHz 36106798872		○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Phantom	02/2003-12/2018	433MHz OYGTSSRE4TC		○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Spectre	08/2023-12/2026	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Spectre	08/2023-12/2026	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
Rolls Royce	Wraith	04/2014-12/2023	433MHz	RR5	○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Wraith	01/2012-12/2021	433MHz 36106790054	RR5	○	●	○	A	433MHz	Huf/Beru	●	●
Saab	9-3	06/2009-12/2012	433MHz	YS3F	○	●	○	A	433MHz	Schrader	●	●
Saab	9-3	10/2006-05/2009	433MHz	YS3F	○	●	○	A	433MHz	Schrader	●	●
Saab	9-3	01/2003-09/2006	433MHz	YS3F	○	●	○	A	433MHz	Schrader	●	●
Saab	9-5	10/2009-12/2013	433MHz	YS3G	●	●	●	0/A	433MHz	Schrader	●	●
Saab	9-5	11/2006-09/2009	433MHz	YE3E	○	●	○	A	433MHz	Schrader	●	●
Saab	9-5	07/2002-10/2006	433MHz	YE3E	○	●	○	A	433MHz	Schrader	●	●
Smart	Forfour	01/2005-12/2023	433MHz	A453	●	●	○	0/A	433MHz	Schrader	●	●
Smart	Fortwo	03/2014-12/2023	433MHz	A453	●	●	○	0/A	433MHz	Schrader	●	●
Smart	Fortwo	01/2007-02/2014	433MHz	A451	●	●	○	0/A	433MHz	Schrader	●	●
Suzuki	Across	10/2020-12/2026	433MHz 4260702070		●	●	○	0	433MHz	Pacific	●	●
Suzuki	Across	01/2020-12/2026	433MHz		●	●	○	0	433MHz	Pacific	●	●

Suzuki	Alto	06/2014-12/2020	433MHz	YC5	●	●	○	0	433MHz	Continental	●	●
Suzuki	Alto	01/2014-06/2015	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Suzuki	Baleno	01/2016-12/2026	433MHz	YR	●	●	○	0	433MHz	Continental	●	●
Suzuki	Escudo	02/2021-12/2025	433MHz 4313052S01		●	●	○	0	433MHz	Continental	●	●
Suzuki	Escudo	01/2017-12/2025	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	Fronx	01/2023-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	Fronx	01/2023-12/2026	433MHz 4313961M00		●	●	○	0	433MHz	Continental	●	●
Suzuki	Grand Escudo	01/2023-12/2026	315MHz 4313054J21		●	●	○	0	315MHz	Schrader	●	●
Suzuki	Grand Escudo	01/2017-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	Ignis	02/2021-12/2026	433MHz	MF	●	●	○	0	433MHz	Continental	●	●
Suzuki	Ignis	01/2016-12/2026	433MHz	YJ	●	●	○	0	433MHz	Continental	●	●
Suzuki	Jimmy	02/2021-12/2026	433MHz		●	●	○	A/0	433MHz	Continental	●	●
Suzuki	Jimmy	01/2014-01/2021	433MHz	YR7/YW5	●	●	○	0	433MHz	Continental	●	●
Suzuki	Kizashi	01/2021-12/2025	315MHz		●	●	○	0	315MHz	Schrader	●	●
Suzuki	Kizashi	01/2009-12/2019	433MHz	YW1	●	●	○	0	433MHz	Continental	●	●
Suzuki	Kizashi	01/2009-12/2019	315MHz		●	●	○	0	315MHz	Continental	●	●
Suzuki	S-Cross	09/2021-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	S-Cross	01/2013-12/2026	433MHz 4313961M00		●	●	○	0	433MHz	Continental	●	●
Suzuki	Solio	01/2025-12/2026	433MHz		●	●	○	0	433MHz	Unknown Manufacturer	●	●
Suzuki	Splash	09/2013-12/2019	433MHz	YV1/YV4/YV5	●	●	○	0	433MHz	Continental	●	●
Suzuki	Super Carry	06/2019-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	Swace	10/2020-12/2026	433MHz 4260702070		●	●	○	0	433MHz	Pacific	●	●
Suzuki	Swace	09/2019-12/2026	433MHz		●	●	○	0	433MHz	Pacific	●	●
Suzuki	Swift	02/2021-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	Swift	08/2013-12/2026	433MHz	YP6/YP7/YS	●	●	○	0	433MHz	Continental	●	●
Suzuki	Swift Sport	02/2020-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	Swift Sport	01/2017-01/2020	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	SX4	11/2021-07/2024	433MHz 4313052S01		●	●	○	0	433MHz	Continental	●	●
Suzuki	SX4	01/2013-12/2025	433MHz	YY1, YY3	●	●	○	0	433MHz	Continental	●	●
Suzuki	SX4	01/2006-12/2014	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
Suzuki	SX4 S-Cross	09/2021-12/2026	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	SX4 S-Cross	01/2013-12/2025	433MHz	YAA	●	●	○	0	433MHz	Continental	●	●
Suzuki	Vitara	02/2021-12/2025	433MHz		●	●	○	0	433MHz	Continental	●	●
Suzuki	Vitara	09/2013-12/2025	433MHz	YFA/YG4/YH4	●	●	○	0	433MHz	Continental	●	●
Suzuki	Wagon R	09/2020-12/2025	433MHz		●	●	○	0	433MHz	Unknown Manufacturer	●	●
Tesla	Model 3	01/2021-12/2026	2. 4GHz		○	●	○	A	2. 4GHz	Sysgration	●	●
Tesla	Model 3	05/2019-10/2020	315MHz 107481400B		○	●	○	A	315MHz	Continental	●	●
Tesla	Model S	01/2021-12/2026	2. 4GHz		○	●	○	A	2. 4GHz	Sysgration	●	●
Tesla	Model S	12/2014-01/2021	433MHz		○	●	○	A	433MHz	Continental	●	●
Tesla	Model S	12/2014-01/2021	433MHz 107481200B		○	●	○	A	433MHz	Continental	●	●
Tesla	Model S	03/2012-01/2021	315MHz 107481400B		○	●	○	A	315MHz	Continental	●	●
Tesla	Model S	01/2012-11/2014	433MHz		○	●	○	A	433MHz	Baolong	●	●

Tesla	Model S	01/2008-12/2014	315MHz		○	●	○	A	315MHz	Continental	●	●
Tesla	Model X	01/2021-12/2026	2. 4GHz		○	●	○	A	2. 4GHz	Sysgration	●	●
Tesla	Model X	04/2016-06/2024	315MHz 107481400B		○	●	○	A	315MHz	Continental	●	●
Tesla	Model X	01/2016-12/2023	433MHz		○	●	○	A	433MHz	Continental	●	●
Tesla	Model X	09/2015-12/2021	433MHz 107481200B		○	●	○	A	433MHz	Continental	●	●
Tesla	Model Y	01/2020-12/2026	2. 4GHz		○	●	○	A	2. 4GHz	Sysgration	●	●
Tesla	Roadster	01/2010-12/2012	433MHz Baolong		○	●	○	A	433MHz	Baolong	●	●
Tesla	Roadster	01/2008-12/2010	433MHz Huf		○	●	○	A	433MHz	Huf/Beru	●	●
Toyota	bZ4X	12/2024-12/2026	315MHz PMV- G001/E005/H00 0		●	●	○	0	315MHz	Pacific	●	●
Toyota	bZ4X	03/2022-12/2026	433MHz PMV- E100		●	●	○	0	433MHz	Pacific	●	●
Toyota	bZ4X	03/2022-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Toyota	Camry	09/2014-12/2026	315MHz PMV- C015/E000		●	●	○	0/A	315MHz	Pacific	●	●
Toyota	Camry Hybrid	09/2014-12/2026	315MHz PMV- C015/E000		●	●	○	0/A	315MHz	Pacific	●	●
Toyota	Century	10/2023-12/2026	315MHz PMV- G001/E005/H00 0		●	●	○	0	315MHz	Pacific	●	●
Toyota	Century	06/2018-12/2024	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Toyota	Century	01/2018-12/2024	315MHz PMV- C010		●	●	○	0	315MHz	Pacific	●	●
Toyota	Crown	06/2018-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Toyota	Crown	12/2012-12/2024	315MHz PMV- C010		●	●	○	0	315MHz	Pacific	●	●
Toyota	GR 86	10/2021-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Toyota	Granace	12/2019-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Toyota	Hiace	05/2020-12/2025	433MHz 4260726040		●	●	○	0	433MHz	Pacific	●	●
Toyota	Hiace	06/2014-12/2025	433MHz 4260726030		●	●	○	0	433MHz	Pacific	●	●
Toyota	Hilux	05/2019-12/2022	315MHz PMV- C010		●	●	○	0	315MHz	Pacific	●	●
Toyota	Land Cruiser	02/2024-12/2026	315MHz PMV- G001/E005/H00 0		●	●	○	0	315MHz	Pacific	●	●
Toyota	Land Cruiser	08/2015-12/2025	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Toyota	Land Cruiser Prado	10/2017-12/2023	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Toyota	Land Cruiser Prado	08/2008-08/2009	433MHz PMV- 107K/1019		●	●	○	0	433MHz	Pacific	●	●
Toyota	Mirai	11/2020-12/2026	315MHz PMV- C015/E000		●	●	○	0	315MHz	Pacific	●	●
Toyota	Prius	05/2014-01/2022	433MHz PMV- C210		●	●	○	0	433MHz	Pacific	●	●

Toyota	RAV4	01/2018-12/2026	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
Toyota	Supra	03/2019-12/2025	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
Toyota	Supra	03/2019-12/2025	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Toyota	Town Ace	01/2022-12/2026	433MHz PMV-E100		●	●	○	0	433MHz	Pacific	●	●
Toyota	Yaris Cross	07/2021-12/2025	433MHz PMV-E100		●	●	○	0	433MHz	Pacific	●	●
Toyota	Yaris GR	08/2020-12/2026	433MHz PMV-E100		●	●	○	0	433MHz	Pacific	●	●
Toyota	Yaris GR	08/2020-12/2026	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
Volkswagen	Arteon	01/2017-06/2024	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Volkswagen	EOS	01/2007-12/2011	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Volkswagen	Golf	01/2007-12/2011	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Volkswagen	Jetta	01/2011-12/2023	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	New Beetle	01/2006-12/2011	433MHz	VW314	○	●	○	A	433MHz	Continental	●	●
Volkswagen	Passat	01/2015-12/2023	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Volkswagen	Passat	01/2006-12/2011	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Volkswagen	Passat CC	01/2009-12/2016	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Volkswagen	T-ROC	11/2017-12/2023	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Tiguan	01/2018-12/2023	315MHz 5Q0907275A		●	●	○	0/A	315MHz	Huf/Beru	●	●
Volkswagen	Tiguan	01/2017-12/2020	315MHz		●	●	○	0	315MHz	Huf/Beru	●	●
Volkswagen	Touareg	01/2011-12/2020	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Volkswagen	Touareg	01/2011-12/2017	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Volkswagen	Touran	06/2020-12/2026	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Volvo	C30	01/2011-03/2014	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	C30	01/2006-03/2014	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
Volvo	C30	01/2006-12/2010	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	C40	01/2022-12/2024	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	C70	01/2011-12/2014	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	C70	01/2008-12/2010	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	C70	01/2006-12/2014	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
Volvo	C70	01/2006-12/2007	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	EX30	06/2023-12/2026	433MHz		○	●	○	A	433MHz	Schrader	●	●
Volvo	EX30	06/2023-12/2026	315MHz		○	●	○	A	315MHz	Schrader	●	●
Volvo	EX90	09/2023-12/2026	433MHz		○	●	○	C	433MHz	BHSENS	●	●
Volvo	S40	01/2011-12/2014	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	S40	01/2003-12/2014	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
Volvo	S40	01/2003-12/2010	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	S60	01/2019-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	S60	01/2010-12/2020	433MHz 31302096		●	●	○	0/A	433MHz	Continental	●	●
Volvo	S60	01/2010-12/2019	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
Volvo	S60	01/2001-12/2010	315MHz 31200923		●	●	○	A	315MHz	Schrader	●	●
Volvo	S60	07/2000-02/2010	433MHz 31329981		●	●	○	A	433MHz	Schrader	●	●

Volvo	S80	01/2010-12/2016	433MHz 31302096		●	●	○	0/A	433MHz	Continental	●	●
Volvo	S80	01/2007-12/2009	433MHz 31302096		●	●	○	0/A	433MHz	Continental	●	●
Volvo	S80	01/2006-01/2017	433MHz 31341893		●	●	○	0/A	433MHz	Continental	●	●
Volvo	S80	01/1999-12/2013	315MHz		●	●	○	A	315MHz	Schrader	●	●
Volvo	S90	01/2016-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V40	01/2015-12/2020	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V40	01/2012-12/2021	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	V40 Cross Country	01/2017-12/2021	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V40 Cross Country	01/2012-12/2017	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
Volvo	V50	01/2011-12/2016	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	V50	01/2004-12/2014	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
Volvo	V50	01/2003-12/2010	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	V60	01/2019-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V60	01/2011-12/2022	433MHz 31341893		●	●	○	0/A	433MHz	Continental	●	●
Volvo	V60 Cross Country	01/2019-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V60 Cross Country	01/2015-12/2018	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	V70	01/2007-12/2016	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
Volvo	V90	01/2016-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V90 Cross Country	01/2016-12/2023	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC40	01/2017-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC60	01/2017-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC60	01/2009-12/2010	315MHz		●	●	○	0/A	315MHz	Schrader	●	●
Volvo	XC60	01/2008-12/2017	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	XC70	01/2008-12/2018	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Volvo	XC90	01/2016-12/2026	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC90	01/2015-12/2022	433MHz 31362304		●	●	○	0/A	433MHz	Schrader	●	●
Volvo	XC90	01/2015-12/2016	315MHz 31200923		●	●	○	0/A	315MHz	Schrader	●	●
Volvo	XC90	01/2015-12/2016	433MHz 31329981		●	●	○	0/A	433MHz	Schrader	●	●
Volvo	XC90	01/2003-12/2014	433MHz 31329981		●	●	○	A	433MHz	Schrader	●	●
Volvo	XC90	01/2003-12/2014	315MHz 31200923		●	●	○	A	315MHz	Schrader	●	●
ZEEKR	009	04/2024-12/2026	433MHz 8894215959		●	●	○	A	433MHz	BHSENS	●	●
ZEEKR	009	11/2022-12/2024	433MHz		●	●	○	A	433MHz	Schrader	●	●
ZEEKR	X	04/2023-06/2026	433MHz		●	●	○	A	433MHz	Schrader	●	●